

## **WINDOW LIFT MOTOR REPLACEMENT PROCEDURE**

### **1995-93 RANGER**

When servicing 1993, 1994 & 1995 models, it will be necessary to remove the “v” shaped white spacer located between the motor and the regulator mounting plate. Do not re-use existing screws – replacement screws included with motor.

Torque Specifications: 5.1-7.3 N-m(45-65 lb-in.)