

WINDOW LIFT MOTOR AND REGULATOR REPLACEMENT PROCEDURE

1992-1996 TOYOTA CAMRY 2 DOOR

Before removing regulator and motor, check fuses, switches and connections.

DOOR TRIM REMOVAL

Remove any screws attaching the trim. On some models remove door handle cover plate and trim plugs that cover screws. It is recommended to use a no. 2 phillips screw driver. Check for any hidden screws that were missed. Carefully pry panel from door (use proper trim removal tool if available) and disconnect wiring from switches and lights.

MOTOR AND REGULATOR REMOVAL

Important - Before removing glass attaching bolts or channel rollers, secure glass with tape or a suitable wedge like a window wedge tool. When the glass is separated from the regulator move the glass to the closed position and retain in a similar manner.

Check to make sure the glass channels are clean and free from obstructions. All regulator mounting attaching hardware requires a 10mm socket or wrench. The regulator needs to be in position to remove glass mounting bolts (see drawings on opposite side). If the motor has stopped where the glass attaching bolts are not accessible, cut one of the regulator drive cables with a suitable tool. This will allow movement of the glass so glass mounting bolts are accessible. Secure glass and remove glass mounting bolts then the regulator and motor mounting nuts. Slide motor and regulator through opening in door.

MOTOR AND REGULATOR INSTALLATION

Insert new motor and regulator into the door while making sure the glass is still in the closed position. Loosely fasten regulator to door beginning with mounting holes by the motor and then loosely fasten the regulator nuts. The glass mounting holes on the replacement motor and regulator should be in position for access through the door. Slide down glass and fasten to regulator. Tighten down all nuts. Attach window lift wiring to switch on unattached trim and test operation. Reconnect remaining wiring and affix trim to door.

88316 / WLA1286 & 88317 / WLA1398 CAMRY FRONT MOTOR & REGULATOR

View - 88316 / WLA1286 Left Front Facing Door from Outside Car

